SNC-WL862

Release Note

Ver.1.0.2

2020/1/20

Sony Corporation

Revision history

#	Release date	Version	Major revision and comment
1	2019/09/10	1.0.1	Initial release
2	2020/01/20	1.0.2	Newly Added Function Bug Fix
3			
4			

CONTENTS

1. About this Release Version

1.1. General
This release version is 1.0.2
Target model: SNC-WL862

1.2. Software version upgrade method
To upgrade the camera software to this version, use SNC toolbox Ver.1.7.0 or later. For the version upgrade procedure, refer to the Application Guide.

1.3. Operating environment
The following operation environment is necessary for the computer used for viewing the camera images or for controlling.

- OS
  Microsoft Windows 8.1 (32 bit version, 64 bit version)
  Microsoft Windows 10 (32 bit version, 64 bit version)
  Verified editions:
    Windows 8.1 Pro
    Windows 10 Pro
- Web browser
  Microsoft Internet Explorer Ver 11.0 (32 bit)

1.4. Compatibility
Regarding the functions provided in SNC-WL862 Ver1.0.1, this version does not contain any change for the CGI command, RTSP or other network protocol, or data format for streaming. It is compatible with SNC-WL862 Ver1.0.1 regarding mutual connectivity with external connected devices.

2. Additional Function

2.1.　　Functions added / changed in Ver. 1.0.2

- The security has been enhanced.
- The default setting of Web and RTSP authentication has been changed from Basic authentication to Digest authentication.

3. Corrected Problems

3.1.　　Problems corrected in Ver. 1.0.2

- There was a problem that SNC-toolbox could not find SNC-WL862 camera in the environment without DHCP server.
- There was a problem that upload function of custom language file did not work.
- There were problems in connection with GENETEC Security Center.
    - There was a problem with the display of Mac address.
    - H.265 did not work in Security Center.
    - Motion Detection did not work in Security Center.
    - There was a problem that an error occurred in Tampering Detection in Security Center.
    - There was a problem that Audio Packet did not appear in Security Center.
- There was a problem in Onvif Motion alarm.

4. Functional Limitations

4.1.   When searching for SNC-WL862 Ver.1.0.1

If you cannot find SNC-WL862 Ver.1.0.1 in an environment without a DHCP server, use the Camera Search Tool for SNC-WL862 ver.1.0.1 (Installation Wizard 2) to search for the Ver.1.0.1 camera.

After searching, access the camera with a web browser and change the network settings from the camera setting menu.

4.2.   When searching for SNC-WL862 Ver.1.0.2

When you search for SNC-WL862 Ver.1.0.2 of the initial setting (factory default setting) with SNC-Toolbox in an environment without a DHCP server, change the network settings according to the following procedure.

(1)   When you search for a camera in SNC-Toolbox, you will find SNC-WL862 with IP 169.254.x.x.

(2)   On the [Tools] > [Device Settings] of SNC-Toolbox, enter the following information in [Device Account] and click OK.

     Administrator name: admin

     Administrator Password: [blank]

(3)   Make network settings on the [Tools] > [Network Settings] screen.